

## Annexure -2

Construction work outer work complete plaster and painting work complete and inside and outer side window and door we fixed so that we remove Strong barricade form construction side.



